Excelle 2011 1.6LX-AT









The exterior is red, with 147,900 kilometers on the mileage sheet, and the engine has no faults. Exterior: The paint is well maintained, the body structure has not been repaired, and there have been no major accidents. Interior: Clean and tidy. The safety indicator lights are normal, the airbags and other passive safety items are normal, the electronic devices in the vehicle are in good use, and the static and dynamic equipment in the vehicle is complete. Driving: There are no problems with the vehicle's ignition, starting, acceleration, cornering, deceleration, and braking. The acceleration is rapid, the power output is smooth and comfortable, and there is no idle jitter. Overall: The overall vehicle condition is average.

Overview

POST_ID 451240
Model 2011 1.6LX-AT
Miles 147900 km
Transmission Automatic
Steering LHD (Left Hand Drive)

Make SAIC-GM Buick
First Registered May 1, 2011
Condition Used Non-Accident
Engine 1.6L 110HP L4
FOB Price \$ 2,867

Series Excelle
Fuel Type Gasoline
Exterior Color Red/Purple
Drive Type Front 2WD

Contact Details

Chinese Car Exports | SellingCar180

SellingCar180

SellingCar180